

Chugoku Regional Division Research of Natural Disaster Research Council
No.1
Contents

Characteristics of Heavy Rainfall and Debris Flow Disaster in Hiroshima City,20 August 2014 <i>Haruhiko YAMAMOTO and Hokuto KOBAYASHI</i>	1
On Squall Line Observed by X-band and C-band Radars in Hiroshima During the Heavy Rainfall in August 2014 <i>Kenji TANAKA</i>	5
Characteristics of a Line-shaped Rainfall System Over Hiroshima in August 2014 <i>Yukari SHUSSE, Takeshi MAESAKA, Kaori KIEDA, Ryohei MISUMI, Namiko SAKURAI and Koyuru IWANAMI</i>	9
Verification of Precipitation of Global Satellite Mapping of Precipitation: GSMapP <i>Tetsuya IKADA, Martwi Diah SETIAWATI and Fusanori MIURA</i>	11
Characteristics of Debris-flow Disasters Based on Local Historical Materials of Yagi and the Around Districts in Hiroshima city <i>Kenji WAKIMIZU and Koji NISHIYAMA</i>	15
Questionnaire Survey on Tsunami Disaster Prevention Awareness for Residents in Indonesia <i>Makoto IKEDA and Koji ASAII</i>	19
Characteristics of the Debris Flow Traveling in 2014'S Hiroshima Disasters <i>Tetsuya KUBOTA and Santa IIZUKA</i>	23
Stereoscopic Presentation of Slope Map and Air-borne Picture of the 2014 Debris Flow Disaster Area in Hiroshima City, and an Attempt to Evaluate the Fluidity and the Erosion Properties of Granite Origin Weathered Soils <i>Motoki KAZAMA, Hiroaki KABUKI, Tomoya YAMAZAKI and Toshikazu MORITA</i>	27
Flow Characteristics of Debris Flow Occurred at Yagi-3chome, Asaminamiku, Hiroshima in Aug. 2014 <i>Hiroshi TAKEBAYASI and Masaharu FUJITA</i>	31
Geomorphological Characteristics of Debris-Flow Basins in a Disaster Caused by Heavy Rainfall on August 2014 in Hiroshima Cities, Japan <i>Tsuyoshi WAKATSUKI, Masato SATO and Mariko UEDA</i>	35
Geological Control of Landslides Induced by the 2014 Hiroshima Rainstorm <i>Masahiro CHIGIRA, Yuki MATSUSHI, Ching-Ying TSOU and Takuma WATAKABE</i>	39
Erosion Landforms and Geological Conditions in the Hiroshima Disaster Area Due to the Heavy Rain in August 2014 <i>Takahito KUROKI, Hiroaki IKEMI and Nozomi ISO</i>	43
Preliminary Study on the History of Debris Flow Activity in Hiroshima <i>Kyoko KAGOHARA, Motoyuki SUZUKI, Kazuyuki SAKAGUCHI and Hiroaki MATSUGI</i>	47
Characteristics of Victims Caused by Heavy Rainfall Disaster in Hiroshima City on August 20, 2014 <i>Motoyuki USHIYAMA</i>	51
History of Urban Development in Residential Area Affected by Heavy Rainfall and Debris Flow Disaster in Hiroshima City in August 2014 <i>Hitomi MURAKAMI and Kazuki MURATA</i>	55
Consciousness Changes Through Contiuing Disaster Prevention Education and Evacuation Drill on KUBO Junior High School Second Grade During the Current Year <i>Naoki MEYAMA, Masato MURATA, Akinori GOTO, Ken-ichi HASHIMOTO and Shunji UE</i>	59
Detection of Debris Flow Disaster in Hiroshima City in 2014 by using ALOS-2/PALSAR-2 Sensor <i>Yuichiro MICHIMURA and Fusanori MIURA</i>	63
Detection of Ground Surface Changes using ALOS/PRISM Sensor <i>Akiho KOMIYA and Fusanori MIURA</i>	67
Simple Detection Method of Land Slide Area by using Optical Sensor Images <i>Yosuke KUROKI, Tsuyoshi EGUCHI and Fusanori MIURA</i>	71