

Chugoku Regional Division Research of Natural Disaster Research Council
No.5

Contents

Questionnaire survey on the Problems on Evacuation from Flood Disaster in Elderly Care Facilities	1
<i>Hiroyuki SAKAKIBARA, Shuki MORIOKE, Daisuke KAMIYA, Yoshihisa AKAMATSU, Ayano KIJIMA, Satoko ISOMURA</i>	
Flood risk assessment of elderly care facility locating in predicted flood inundation area	
Part 1 Example of Ikutora area, Minamifurano Town	7
<i>Haruhiko YAMAMOTO</i>	
Flood risk assessment of elderly care facility locating in predicted flood inundation area	
Part 2 Example of Kitakawa area, Nobeoka City	11
<i>Haruhiko YAMAMOTO</i>	
A study of the formulation of school disaster prevention plan and business continuity plan from the view of obtained documents	13
<i>Naoki MEYAMA, Maho NAGAYASU</i>	
Study on flood disaster in Mabi Area, Kurashiki City by torrential rains in West Japan in July 2018	
- Some lessons from Arii questionnaire	17
<i>Hitomi MURAKAMI</i>	
Sediment disasters caused by 2018 July torrential rainfall in Higashi district, Hiroshima City	21
<i>Kenta NISHIYAMA, Motoyuki SUZUKI, Satoru KATAOKA, Hiroaki MATSUGI, Hiroshi OGASAHARA, Tomoki NISHIKAWA, Kyoko KAGOHARA</i>	
Topographic analysis tests using SfM photogrammetry based on measuring by GNSS Receiver	25
<i>Takahito KUROKI, Kensuke GOTO, Hiroaki IKEMI</i>	
Flood analysis in Mabi Town, Okayama by using SAR satellite image	29
<i>Kaiki KINJHO, Hajime SHIROZU, Koji ASAI</i>	
Detection of slope failure in Norio-gawa river basin by using satellite image	33
<i>Tomohito ISHII, Hajime SHIROZU, Takuzo AMANO, Koji ASAI</i>	
A new issue 'SUFFUSION' of degradation due to aging in embankment reservoir	37
<i>Taichi ISHIMARU, Motoyuki SUZUKI, Yuichi KAMIKI, Tomoki WAKAMATSU</i>	
Extraction method for slope collapse behind the agricultural reservoir due to heavy rainfall using remote sensing	41
<i>Hajime SHIROZU, Yusuke MORIYAMA, Koji ASAI</i>	